



Department of Transportation

BUS INSPECTION SYSTEM OPERATOR PROFILE

April 28, 2021

Operator: 27532

Profile Period: 04/01/2020 to 03/31/2021

ANNA'S AIRPORT & LIMO SERVICE INC.

67 FAIRFIELD DR
PATTERSON, NY 12563

Operator Category Status: Preferred

OUT OF SERVICE RATE FOR THE PROFILE PERIOD ABOVE IS:

0.00%

(This rate reflects the results from full and critical item inspections for this operator only. Failed inspections occur when at least one "A" defect is identified)

INSPECTION PERFORMANCE

Inspection Summary of Full and Critical Item Inspections:

	<u>Total</u>	<u>Percent</u>
Inspections:	4	
Passed (With No "A" Defects):	4	100.00%
Failed (With At Least 1 "A" Defect):	0	0.00%

April 28, 2021
Operator: 27532

ANNA'S AIRPORT & LIMO SERVICE INC.
67 FAIRFIELD DR
PATTERSON, NY 12563
Operator Category Status: Preferred

DETAIL SUMMARY

Inspections

	<u>Total</u>
Full Inspection	2
Critical Above	1
Critical Below	1
Re-Inspection	0
Post Accident	0
Fleet	0
Random	0
New in Service	2
Distributor	0
Special	0

Non-Inspection Transactions

	<u>Total</u>
Non Present	0
Temp OOS	0
Perm OOS	2
Certificate Replacement	0
Transfer	0
Misc.	0

DEFECT SUMMARY (Full or Critical Inspections Only)

<u>Item</u>	<u>Total</u>
"B" DEFECTS	
26.08-1-B TAIL LIGHTS/LICENSE PLATE LIGHTS:1. ANY LIGHT OR CONTROL THAT FAILS TO FUNCTIONS AS DESIGNED/INTENDED	1